GeoScience, Inc.

SUB E. 22nd Avenue Substation Project Slope Stability Review

Embankment below Location C. Material likely derived from B. View NW.

Generated from GeoScience Site Photos 7/28/19